

INTERNATIONAL INDIAN SCHOOL - JEDDAH

(AFFILIATED TO CENTRAL BOARD OF SECONDARY EDUCATION, NEW DELHI-INDIA)

MEMBER, COUNCIL OF C.B.S.E. SCHOOL IN GULF

MINISTRY OF EDUCATION - K.S.A. - LICENCE NO. 045 / J

P.O. Box 14861 JEDDAH 21434, SAUDI ARABIA

Boys' Section Tel. 6751536 / 6711934 / 6712097 - Fax. 6751539

Girls' Section Tel. 6721607 / 6718345 - Fax. 6710487

Girls' Section I-II Tel. 6737752 - KG Tel. 6747737



المدرسة الهندية العالمية - بجدة

المملكة العربية السعودية

وزارة التربية والتعليم - ترخيص رقم ج / ٤٥

ص.ب: ١٤٨٦١ جدة ٢١٤٣٤

ت: قسم البنين ٦٧٥١٥٣٦ / ٦٧١١٩٣٤ / ٦٧١٢٠٩٧ - فاكس: ٦٧٥١٥٣٩

ت: قسم البنات ٦٧٢١٦٠٧ / ٦٧١٨٣٤٥ - فاكس: ٦١٧٠٤٨٧

ت: قسم البنات فصل ١ و ٢: ٦٧٢٧٧٥٢ - روضة وتمهيدي: ٦٧٤٧٧٣٧

Date: July 8, 2019

Request for Quotation for Electrical and Air Conditioner Inspection

International Indian School Jeddah invites quotation/Expression of Interest from registered, Electrical Engineering Firm/ Consultant for Electrical safety Inspection and Report on functioning of Air Conditioners in all the Sections of the School. Interested Parties may submit the sealed quotation with detailed scope of work, in an envelope super scribed "QUOTATION FOR ELECTRICAL AND AIR CONDITIONER INSPECTION", at the office of Principal on or before 22-7-2019 by 3 PM through Post or in person.

Scope of Work

1. Detailed inspection of the School's Electrical system and its comparison with the electrical requirement as per the current electrical standards and local authority norms.
2. Identification of overloading of any electrical circuit or equipment.
3. Identify any potential electrical shock risk and fire hazard.
4. Identify any defective electrical work.
5. Highlight any lack of earthing and bonding.
6. Identification of electrical equipment and wiring which may have degraded over a period of time.
7. Identify oversize fuse or breaker that could lead to fire.
8. Inspection of the electrical panel for appropriate label, amps, and operation.
9. Checking the suitability of switch gear and control gear and serviceability of switch, socket and lighting fittings.
10. Advice for any modification required in the existing electrical system such as upgrading of electrical panel, changing /correction of wiring loop, upgrade or modify Lighting in each area.
11. Checking of all the Air Conditioners in the school and submit the report on the functioning of Air Conditioners.
12. Identify and submit the list of Air Conditioners which need immediate replacement.
13. Total number of Window and Split Air conditioner in the school are 438 and 291, respectively.

The company should have valid license to carry out such work. The work awarded to the firm in past by any agency/establishment may kindly be enclosed.


Dr. Muzaffar Hassan
Principal & HOI